


First step: Set up the multimeter as below




From right side, Red line+ 3, Black line -4




From right side, Red line+ 5, Black line -6



From right side, Red line+ 5, Black line -7



From right side, Red line+ 5, Black line -8



From right side, Red line+ 5, Black line -9

